



COLUMNS



Section	ON EDGE (X-X AXIS)		MONORAIL (Y-Y AXIS)	
	Min. Radii.	Lead In / Out	Min. Radii.	Lead In / Out
100 UC 14	1400	550	500	450
150 UC 23	10000	650	2500	600
150 UC 30	2000	650	1500	600
150 UC 37	1400	700	1200	550
200 UC 46	CALL		3000	600
200 UC 60	2500	1000	1500	700
250 UC 89	4000	1000	3000	700
310 UC 97	6000	1000	3000	900
310 UC 118	6000	1000	3000	800
310 UC 137	6000	1000	3000	800
310 UC 158	5138	1000	CALL	