



ANGLE IRON

TOE OUT
TOE IN

| Section | TOE OUT | | TOE IN | |
|------------|-------------|---------------|-------------|---------------|
| | Min. Radii. | Lead In / Out | Min. Radii. | Lead In / Out |
| 25*25*3 | 150 | 150 | 200 | 200 |
| 50*50*6 | 250 | 250 | 350 | 300 |
| 75*75*6 | 450 | 350 | 500 | 350 |
| 100*100*6 | 1000 | 450 | 1500 | 500 |
| 100*100*10 | 450 | 500 | 650 | 500 |
| 125*125*6 | 1400 | 550 | 2000 | 650 |
| 125*125*12 | 700 | 550 | 900 | 650 |
| 150*150*12 | 900 | 600 | 1500 | 650 |
| 150*150*20 | 900 | 650 | 1000 | 700 |
| 200*200*13 | 3500 | 700 | 4500 | 750 |
| 200*200*20 | 2500 | 700 | 4000 | 750 |